

HS-64 Site Activity Report - Rev. 1

Report Number: ARPT-RL-2011-003

Site: DOE Richland Operations Office**Subject:** Office of Independent Oversight's Office of Environment, Safety and Health Evaluations Activity Report for the Review of the CH2M Hill Plateau Remediation Company Unreviewed Safety Question Procedure**Dates of Activity** 01/10/2011 – 01/14/2011**Report Preparer** William Miller**Activity Description/Purpose:**

The U.S. Department of Energy Office of Independent Oversight, within the Office of Health, Safety and Security, during a site visit from January 10-14, 2011, presented the results of a technical review of the CH2M Hill Plateau Remediation Company (PRC) Unreviewed Safety Question (USQ) Procedure.

Result:

The review of the CH2M Hill PRC USQ process procedure resulted in several substantive questions and comments that included one related to an ambiguous statement in the Waste Encapsulation Storage Facility Documented Safety Analysis with respect to USQ Margin of Safety considerations. The contractor was in the process of revising and updating the USQ process procedure, and committed to review and consider these questions and comments for incorporation into the updated procedure.

HSS Participants**References**

1. William Miller

2. Donald Prevatte

Were there any items for HSS follow up? ☒ Yes ☐ No**HSS Follow Up Items**

1. Review the final CH2M Hill PRC USQ Process Procedure to verify appropriate changes were made.

2. Review the Waste Encapsulation Storage Facility Documented Safety Analysis to verify appropriate changes were made with its reference to the USQ Margin of Safety considerations in coordination of the revision of the PRC USQ Process Procedure.